

FLORIDA DEPARTMENT OF Hazardous Walking Site Review Checklist

(To assist in determining eligibility for school transportation based on hazardous walking conditions in accordance with section 1006.23, Florida Statutes)

Walkways Parallel To The Road

<u>YES</u>	<u>NO</u>	
	X	 Is the location in a residential area with little or no traffic? Is the location in a residential area and on a road or street that is not used as a major artery or cut-through?
	_X	2. Is the location on a road where the traffic volume is fewer than 180 vehicles per direction per hour at 6:00 am - 9:00 am and 2:00 pm - 4:00 pm? Note: If the traffic count during the times students must walk is 180 vehicles per hour or more, in either direction, the answer to this question is "no."
	_X	3. Is the area located in a residential area and on a road that has a posted speed limit of 30 miles per hour or less?
		., 2. or 3. is "YES," the area does not qualify as a hazardous walking location. and 3. are all "NO," continue to next question.
If the post	ed speed limi	t is less than 50 mph:
N/A	N/A_	4. Is there an area at least four feet wide with a "surface upon which students may walk" that prevents the students from having to walk on the road? Note: The surface does not have to be a sidewalk, but simply a surface upon
		which the students may walk. Weeds, tall grass or flooding may be temporary maintenance problems that do not constitute a hazardous walking area. A walking surface does not include drainage ditches, sluiceways, swales or channels. A paved area contiguous with the paved roadway or extended shoulder (also known as a "breakdown lane"), with no separation from the driving area or raised curb, is <u>not</u> a walkway.
If the posto	ed speed limi	which the students may walk. Weeds, tall grass or flooding may be temporary maintenance problems that do not constitute a hazardous walking area. A walking surface does not include drainage ditches, sluiceways, swales or channels. A paved area contiguous with the paved roadway or extended shoulder (also known as a "breakdown lane"), with no separation from the
If the posto	ed speed limit	which the students may walk. Weeds, tall grass or flooding may be temporary maintenance problems that do not constitute a hazardous walking area. A walking surface does not include drainage ditches, sluiceways, swales or channels. A paved area contiguous with the paved roadway or extended shoulder (also known as a "breakdown lane"), with no separation from the driving area or raised curb, is <u>not</u> a walkway.

If the answer to 4., 5. or 6. is "YES," the area does not qualify as a hazardous walking location.

Walkways Crossing Over The Road

(When students must cross the road)

A. For an "uncontrolled crossing site" (no crossing guard, traffic enforcement officer, stop sign or other

traffic control signal present during student walk times):						
<u>YE</u>	<u>:S</u>	<u>NO</u>				
N/A	<u> </u>	N/A_	1.	Does the traffic volume exceed 360 vehicles per direction, per hour (either direction, including all lanes in each direction)?		
N/A	<u>\</u> .	N/A_	2.	Does the road have a posted speed limit of 50 MPH or greater?		
N/A	<u>\</u> .	N/A_	3.	Does the road have six or more lanes (not including turning lanes)?		
If th			-	estions are "NO," the area does not qualify as a hazardous walking location. ve questions is "YES," the area would qualify as a hazardous walking		
				ng site controlled by a stop sign or other traffic control signal, but without forcement officers during the times students must walk:		
N/A		N/A	1.	Does the total traffic volume (total of both directions) exceed 4,000 vehicles per hour?		
If th	ie answer is	s "NO," the ar	rea	does not qualify as a hazardous walking location.		
	C. Any intersection or other crossing site <u>with</u> a crossing guard or other traffic enforcement officer does not qualify as a hazardous walking location, regardless of the posted speed limit.					
D.	Comments	/Notes/Diagr	am	S:		
	See attach	ned materials	S.			

Page 2 of 3


Location Code: 110014


Hazardous Walking Site Review - Documentation and Authorization

School District:	Lake	Site Review Date: 3/10/2016				
Hazard Location:	SR-46 east of US Hwy 441 Mount Dora					
Hazard Location Is:	X Parallel to the road	Traffic Count:687 (afternoon)				
	Crossing over the road	Traffic Count:				
Hazard Jurisdiction:	Municipal (Identify:) CountyX _ State				
Permanent Hazard?	_XYesNo If no,	anticipated correction date:				
School District Repres	entative: William C. Davis Print Name	Signature				
Email: davis		Phone: 352-253-6527				
Roadway Jurisdiction	Representative: Seth Lynch	Cinadan				
Agency/Entity	Print Name Florida Department of Transpo	rtation Title:				
Law Enforcement Rep	resentative: Print Name	Signature				
Agency/Entity	Mount Dora Police Departmen					
Email:		Phone:				
Metropolitan Planning Organization Representative: Michael F. Woods						
(If applicable)	Print Name	Signature				
Agency/Entity	: Lake-Sumter MPO	Title: Transportation Planner				
Email: _mwoo	ods@lakesumtermpo.com	Phone: 352-315-0170				
Assigned FDOE Hazardous Walking Database Location Code: 110014 Date Entered: 10/08/2015						
Staff assigning and entering hazardous walking location into the database: William C. Davis						

Location Code: 110014 Page 3 of 10

FDOT HWC# 110014









COUNTY: 11 STATION: 0501

DESCRIPTION: ON SR-46, 0.129 MI. W OF ROUND LAKE RD. (RVL)

START DATE: 07/09/2014

START TIME: 1400

DIRECTION: E DIRECTION: W COMBINED 1ST 2ND 3RD 4TH TOTAL 1ST 2ND 3RD 4TH TOTAL TIME TOTAL 27 l 1 1 0 10 5 5 11 18 l ______ 24-HOUR TOTALS: ſS

			PEAK VOLUME	INFORMATION		
	DIRECTION: E		DIRECTION: W		COMBINED	DIRECTIONS
	HOUR	VOLUME	HOUR	VOLUME	HOUR	VOLUME
A.M.	700	427	730	331	715	744
P.M.	1715	420	1645	457	1700	875
DATLY	700	427	1645	457	1700	875

GENERATED BY SPS 5.0.45P

COUNTY: 11 STATION: 0501

DESCRIPTION: ON SR-46, 0.129 MI. W OF ROUND LAKE RD. (RVL)

START DATE: 07/10/2014

START TIME: 1400

DIRECTION: E DIRECTION: W COMBINED 1ST 2ND 3RD 4TH TOTAL 1ST 2ND 3RD 4TH TOTAL TIME TOTAL 30 | 3 9 1 5 0 4 5 9 1 6 6 5 21 16

24-HOUR TOTALS:	5201	5082	10283

DEAK MOLIME INFORMATION

			PEAK VOLUME	INFORMATION		
	DIRECTION: E		DIRECTION: W		COMBINED DIRECTIONS	
	HOUR	VOLUME	HOUR	VOLUME	HOUR	VOLUME
A.M.	730	422	815	328	745	703
P.M.	1700	447	1645	467	1700	891
DAILY	1700	447	1645	467	1700	891

GENERATED BY SPS 5.0.45P

Looking West



Looking West Northwest



Looking East



Looking East Southeast

